


Valley Top End



Note: Foam or metal closures and caulking (ProSeal 34 is recommended) are required between the intersecting ridge cap and the valley flashing to provide adequate weathertightness.